

LDALI-MS4-BT L-DALI Multi-Sensor

Installation instructions

Instructions de montage


Istruzioni di montaggio

Montageanweisung

Instrucciones de montaje

Montagevoorschrift

Monteringsanvisning



max 50° C
min 0° C

RH
10 - 90 %




kg
0.048 kg

mm
[inch]




DALI Load:
typ. 3 mA*
@ 16 V DC,
max. 10 mA
inrush current




*typ. 6 mA with
Bluetooth enabled

Radio Signal:
2.402 -
2.480 GHz
+ 4 dBm



h [m]	d [m]	A [m²]	α[°]
1.5	3.6	10.0	100
2.0	4.8	17.8	100
2.5	6.0	27.9	100
2.7	6.4	32.5	100
3.0	7.2	40.2	100
3.5	8.3	54.7	100
4.0	9.5	71.4	100
4.5	10.7	90.3	100
5.0	11.9	111.5	100







U.S. FC
Contains FCC ID:
H79DFBM-NW726-DT0

E.U. CE


Taiwan
內含藍芽模組
CCAM18LP1230T4

Japan   201-180639


Wiring Diagram





Weidmüller
BL 3.5/04/180
BL 3.5/06/180




6 0.2 - 1.5 mm² [AWG 28 - 14]







Spring



Spring



spring assembly



strain-relief

