

# LPAD7-SOCKET5

## LPAD7-SOCKET5-B Mounting Socket

### Installation instructions

Instructions de montage





Montageanweisung

Montagevoorschrift


Istruzioni di montaggio


Instrucciones de montaje

Monteringsanvisning




13.6 [0.535]






Push screwdriver (not sharp) into slot above wire.  
When wire is free, pull to extract.

1




Solid wire

2




Stranded wire

3



Release




1.5mm



### Wire Gauge Size


| Code | Accepted Wire Gauge            | Max Conductor      | Max Insulation     |
|------|--------------------------------|--------------------|--------------------|
| 21   | 18-26 AWG<br>Solid or Stranded | 1.20mm<br>Diameter | 2.10mm<br>Diameter |

strip length  
4-5mm




### Connectors

|                                 |   |                                                                                              |
|---------------------------------|---|----------------------------------------------------------------------------------------------|
| INPUT 24V AC/DC<br>POWER SUPPLY | 1 | 24V+  * |
|                                 | 2 | 24V-/GND                                                                                     |
|                                 | 3 | not connected (NC)                                                                           |



\* Power OFF and wait 30s before inserting LPAD!

**Mounting height:**



Do not tighten  
screws too much  
to avoid bending  
of the socket!