

LSMI-804 SMI Interface (high voltage)

Installation instructions

Instructions de montage


Montageanweisung


Montagevoorschrift

Istruzioni di montaggio


Instrucciones de montaje

Monteringsanvisning





Serial number of the device




Connectors		
85-240 VAC 50/60Hz	1	Input N Neutral
	2	Input L Line (max. 3W)
SMI 1 16 Motors	11	SMI I+
	12	SMI I-
SMI 2 16 Motors	13	SMI I+
	14	SMI I-
SMI 3 16 Motors	15	SMI I+
	16	SMI I-
SMI 4 16 Motors	17	SMI I+
	18	SMI I-
USB		Compatible with USB Type-C®, connect to L-INX, L-GATE, L-DALI

2 poles: Sauro CIF020070N

8 poles: Weidmüller BLZP 5.08/08/180


Sauro CIF020070N



Weidmüller

BL 5.08

0.2 - 2.5 mm²



4.5 lb-in/0.5 Nm